

CRJ

Hydraulic

Pump



Derco Repair Services has the capability to repair and overhaul the CRJ hydraulic pump, P/N 848847 (MPEV3-012-2B). An FAA approved repair scheme on the housing is available to repair cavitation erosion in the piston bore area. This repair is much less costly than replacing the housing. Several alternates to OEM parts are also available to reduce repair/overhaul cost and turn-time.

For more information about CRJ hydraulic pump repair and other services, contact Repair Sales:
Tel (414) 355-7770 • Fax (414) 355-2648
E-mail repairsales@dercoaerospace.com
www.dercoaerospace.com
FAA Repair Station NK5R070N • EASA.145.4389



DERCO
REPAIR SERVICES, INC.

Simplifying Aerospace