

CRJ

Wheel Speed Transducer



For complete repair and overhaul on the CRJ wheel speed transducer, P/N 140-153, choose Derco Repair Services, Inc. For quick turn-around times, Derco Repair stocks routinely replaced parts including the adapter (P/N 140-15310). Derco Repair also stores overhauled LRUs and offers no fee AOG exchanges.

For more information about CRJ wheel speed transducer repair and other services, contact Repair Sales:

Telephone: (414) 355-7770 • Fax: (414) 355-2648

E-mail: repairsales@dercoaerospace.com

www.dercoaerospace.com

FAA Repair Station NK5R070N • EASA.145.4389

Derco Repair Services Inc.

A Sikorsky Aerospace Services Company