


CRJ

Hydraulic

Pump



Derco Repair Services has recently set up capability on the CRJ hydraulic pump P/N 848847 (MPEV3-012-2B). An FAA approved repair scheme on the housing is available to repair erosion in the piston bore area. This repair is much less costly than replacing the housing. Several alternates to OEM parts are also available to reduce repair/overhaul cost and turn time.

For more information about CRJ hydraulic pump repair and other services, contact Repair Sales
Tel (414) 355-7770 • Fax (414) 355-2648
E-mail repairsales@dercoaerospace.com
www.dercoaerospace.com
FAA Repair Station NK5R070N • EASA.145.4389

Derco Repair Services Inc.

A Sikorsky Aerospace Services Company