



ATR42/72 Component Support Capabilities

Derco Repair Services, Inc.
 8065 West Fairlane Avenue Milwaukee, WI 53223 USA
 tel: (414) 355-7770; fax: (414) 355-2648
 repair@dercoaerospace.com

| PART NUMBER | DESCRIPTION | MANUFACTURER | ATA |
|-----------------|--------------------------|----------------------------------|-----|
| 11S76180650-002 | BOX, MICROSWITCH ASSY | * ATR/OMA | 31 |
| 11S76180650-004 | BOX, MICROSWITCH ASSY | * ATR/OMA | 31 |
| 11S76180650-006 | BOX, MICROSWITCH ASSY | * ATR/OMA | 31 |
| 11S76180650-010 | BOX, MICROSWITCH ASSY | * ATR/OMA | 31 |
| 11S76180650-014 | BOX, MICROSWITCH ASSY | * ATR/OMA | 31 |
| 140-071 | TRANSDUCER, WHEEL SPEED | CRANE/HYDRO-AIRE | 32 |
| 140-07115 | TRANSDUCER, WHEEL SPEED | CRANE/HYDRO-AIRE | 32 |
| 140-07120 | CAP, HUB | CRANE/HYDRO-AIRE | 32 |
| 14430 | SHAFT, ASSY. | * SKF AEROSPACE (FORMERLY SARMA) | 27 |
| 14490 | SHAFT, ASSY. | * SKF AEROSPACE (FORMERLY SARMA) | 27 |
| 2757B01 | VALVE | LIEBHERR | 36 |
| 291F01000-003 | RESERVOIR, HYDRAULIC | * OMA | 29 |
| 291F01000-005 | RESERVOIR, HYDRAULIC | * OMA | 29 |
| 291F01200-001 | FILTER | * OMA | 29 |
| 291F01400-001 | FILTER, GREEN SYSTEM | * OMA | 29 |
| 291F01500-001 | TRANSMITTER, LEVEL | * OMA | 29 |
| 291F02000-003 | ACCUMULATOR, HYDRAULIC | * OMA | 29 |
| 324F02000-005 | ACCUMULATOR, HYDRAULIC | * OMA | 35 |
| 351-33672-001 | PANEL, ALERT | EATON | 31 |
| 351-33672-101 | PANEL, ALERT | EATON | 31 |
| 351-33672-102 | PANEL, ALERT | EATON | 31 |
| 351-33672-103 | PANEL, ALERT | EATON | 31 |
| 351-35848-001 | PANEL, ALERT | EATON | 31 |
| 351-35848-101 | PANEL, ALERT | EATON | 31 |
| 420200 | REGULATOR, CABLE TENSION | * SKF AEROSPACE (FORMERLY SARMA) | 27 |
| 420300 | REGULATOR, CABLE TENSION | * SKF AEROSPACE (FORMERLY SARMA) | 27 |
| 420300M00 | REGULATOR, CABLE TENSION | * SKF AEROSPACE (FORMERLY SARMA) | 27 |
| 421370 | ROD, FORCE DETECTOR | * SKF AEROSPACE (FORMERLY SARMA) | 22 |
| 421370M01 | ROD, FORCE DETECTOR | * SKF AEROSPACE (FORMERLY SARMA) | 27 |
| 421370M02 | ROD, FORCE DETECTOR | * SKF AEROSPACE (FORMERLY SARMA) | 22 |
| 421500 | DETECTOR, FLAP ASSEMETRY | * SKF AEROSPACE (FORMERLY SARMA) | 27 |
| 421500A | DETECTOR, FLAP ASSEMETRY | * SKF AEROSPACE (FORMERLY SARMA) | 27 |
| 421800 | ROD, FORCE DETECTOR | * SKF AEROSPACE (FORMERLY SARMA) | 22 |
| 720500M01 | ACTUATOR | * SKF AEROSPACE (FORMERLY SARMA) | 27 |
| 782689-1 | BRUSH, BLOCK | HAMILTON STANDARD | 61 |
| 782689-2 | BRUSH, BLOCK | HAMILTON STANDARD | 61 |
| 782689-3 | BRUSH, BLOCK | HAMILTON STANDARD | 61 |
| 782689-4 | BRUSH, BLOCK | HAMILTON STANDARD | 61 |
| 782689-5 | BRUSH, BLOCK | HAMILTON STANDARD | 61 |
| 782689-6 | BRUSH, BLOCK | HAMILTON STANDARD | 61 |
| 8107-110-00-10 | SENSOR, PRESSURE | BRION LEROUX | 79 |
| 970500-7M00 | REGULATOR, CABLE TENSION | * SARMA | 27 |
| 970500-7M01 | REGULATOR, CABLE TENSION | * SARMA | 27 |
| 970500-8M00 | REGULATOR, CABLE TENSION | * SARMA | 27 |
| 970500-8M01 | REGULATOR, CABLE TENSION | * SARMA | 27 |
| 979990-1 | VALVE, TEMPERATURE | ALLIEDSIGNAL | 21 |



ATR42/72 Component Support Capabilities

Derco Repair Services, Inc.
8065 West Fairlane Avenue Milwaukee, WI 53223 USA
tel: (414) 355-7770; fax: (414) 355-2648
repair@dercoaerospace.com

| PART NUMBER | DESCRIPTION | MANUFACTURER | ATA |
|-------------------|------------------------|----------------------|-----|
| APT-86-1000-5000A | TRANSDUCER | KULITE | 29 |
| D25AB1110 | RESTRICTOR | BRONZAVIA - AIR EQUI | 27 |
| D25AB1111 | RESTRICTOR | BRONZAVIA - AIR EQUI | 27 |
| D25AB1115 | RESTRICTOR | BRONZAVIA - AIR EQUI | 27 |
| L50-91 | CONTROL, BOX | MORSE TELEFLEX | 27 |
| R22022 | ROD | * TAC | 52 |
| S7618065000200 | BOX, MICROSWITCH ASSY. | * ATR | 31 |
| S7618065000400 | BOX, MICROSWITCH ASSY | * ATR | 31 |
| S7618065000600 | BOX, MICROSWITCH ASSY. | * ATR | 31 |
| S7618065000800 | BOX, MICROSWITCH ASSY | * ATR | 31 |
| S7618065001000 | BOX, MICROSWITCH ASSY | * ATR | 31 |
| S7618065001400 | BOX, MICROSWITCH ASSY | * ATR | 31 |